

Case No.	Respondent	Summary of Findings	Summary of Board Action
JULY 24, 2007			
M06-096	Richard G. Kelly P.E. (Civil) #26853	Respondent failed to apply the technical knowledge and skill that would be applied by other qualified registrants who practice the same profession in the same area and at the same time. On or about March 2002, Respondent prepared a Subsurface Soil Exploration; and on or about April 2002, Respondent prepared an Addendum to the report. Respondent's work was deficient in that the field exploration program did not generate the quantitative information that is typically collected by geotechnical consultants when performing pre-construction geotechnical evaluations; and the work did not include laboratory testing for moisture density, swell testing, and compression consolidation testing.	Letter of Reprimand Professional Education – Respondent shall take and successfully complete a course in the area of geotechnical engineering. Cost of Investigation – Pay cost of investigation in the amount of \$670.00.
M06-272	Clifford Don Walding Land Surveyor #33880	On or about April 2005, Respondent failed to conduct a survey in accordance with the Arizona Boundary Survey Minimum Standards. Respondent prepared a Results of Survey map which is deficient in that Respondent failed to include the required surveyor's statement; failed to explain in detail the reason for not accepting a monument; failed to indicate the record documents referenced where there were differences in the record and measured bearings and distances; failed to secure his RLS number on identifying markers on recovered monumentation that was not tagged or marked; and failed to record the survey in the Maricopa County Recorder's Office after setting new monuments.	Letter of Reprimand Amend Survey – Respondent shall amend his survey and record it with the Maricopa County Recorder's Office. Cost of Investigation – Pay cost of investigation in the amount of \$215.00.
M07-007	James D. Downing P.E. (Agricultural) #19202	On or about October 2003, Respondent failed to apply the technical knowledge and skill that would be applied by other qualified registrants who practice the same profession in the same area and at the same time. Respondent prepared As Built Drawings and sealed an Engineer's Certificate of Completion and Final Inspection ("ECC") for a water distribution system which were deficient in that Respondent failed to note that the completed project deviated from the plans which received the Approval to Construct; and failed to indicate that the space layout was not consistent with the approved plans. On or about February 2006, Respondent failed to apply the technical knowledge and skill that would be applied by other qualified registrants who practice the same profession in the same area and at the same time. Respondent prepared and sealed As Built plans for a drinking water system which were deficient in that Respondent failed to accurately reflect the system that was constructed and failed to submit accurate information regarding the actual well that was constructed.	Letter of Reprimand Administrative Penalty – Pay an administrative penalty of \$1,500.00. Cost of Investigation – Pay cost of investigation in the amount of \$490.00.
M07-062	Felix G. Steele Land Surveyor #28234	On or about December 2005, Respondent failed to conduct a survey in accordance with the Arizona Boundary Survey Minimum Standards. Respondent performed and prepared a Record of Survey that is deficient in that Respondent failed to show an encroachment of a barn/shed onto the southeast boundary of the property.	Letter of Reprimand Cost of Investigation – Pay cost of investigation in the amount of \$125.00.